


# TWISTER SERIES Ver.2

ALL-IN-ONE ARGB LIQUID CPU COOLER




## INSTALLATION GUIDE


### Part List

|               |  |  |  |                            |
|---------------|--|--|--|----------------------------|
| <b>DX-360</b> | <b>A</b> Radiator FAN x3               | <b>B</b> Radiator Screws x12           | <b>C</b> FAN Screws x12                | <b>D</b> PWM Connector x1  |
| <b>DX-240</b> | <b>A</b> Radiator FAN x2               | <b>B</b> Radiator Screws x8            | <b>C</b> FAN Screws x8                 | <b>E</b> Thermal Grease x1 |
|               | <b>G</b> Intel Backplate x1            | <b>H</b> Intel Clip x2                 | <b>I</b> Fastener Screws x4            | <b>F</b> AMD Fastener x2   |
|               | <b>K</b> Rubber Washer x4              | <b>L</b> Intel Mounting Screws x4      | <b>M</b> AMD Mounting Screws x2        | <b>J</b> AMD Support x2    |
|               | <b>N</b> Intel 1700 Standoff Screws x4 | <b>O</b> Intel 115x Standoff Screws x4 | <b>P</b> Intel 20xx Standoff Screws x4 |                            |


### STEP 1 - INTEL/AMD




### STEP 2 - INTEL/AMD




### STEP 3 - INTEL/20XX




### STEP 4 - INTEL 115X




### STEP 5 - INTEL 1700



### STEP 6 - AMD



### STEP 7 - Wiring



Fly to unlimited!